


## **TORXmeter® system overview complete**



Legend		
No. 1	Terminal Box	Scope of supply
No. 2	MWE-Box	Scope of supply
No. A	Pre-wired cable between MWE Box and EXFR sensors (appr. 3,7m)	Scope of supply
No. B	Pre-wired cable between MWE Box and EXFR sensors (appr. 3,7m)	Scope of supply
No. 3	2 pcs: Brackets (bracket must be welded to ships structure-No.4)	Scope of supply
No. 4	Support for Sensor holder	Scope of yard/owner supply
No. 5	1 PCS: cable between Terminal Box and MWE Box (4x2x0,75mm <sup>2</sup> )	Scope of yard/owner supply
No. 6	2 pcs. holder for EXFR sensor (screwed on No. 3)	Scope of supply
No. 7	2 pcs. EXFR sensors	Scope of supply
No. 8	2 pcs. Sensor belts	Scope of supply

